

Total Quality Management and Six Sigma
Post Graduate Program 2014-15

Session 4

Vinay Kumar Kalakbandi
Assistant Professor
Operations & Systems Area

09/11/2014

Vinay Kalakbandi

1

Wishing you all a
“Total Quality” New Year!

Hope you achieve Six sigma heights

09/11/2014

Vinay Kalakbandi

2

Recap

- Statistical process control
 - Manufacturing and service sector applications
 - Implementation challenges

Agenda

- Magnificent seven SPC tools
- Additional tools for services
- Technical aspects of SPC usage
 - Rational subgrouping
 - Phases of SPC implementation
 - Shewart Control Charts
- Phase 2 implementation
 - CUSUM charts
 - EWMA charts
- Short production runs: DNOM charts, Q charts
- Multiple stream processes
- Economic design of control charts
- Adaptive sampling for better control using SPC

Magnificent seven

- Histogram or stem-and-leaf plot
- Check sheet
- Pareto chart
- Cause-and-effect diagram
- Defect concentration diagram
- Scatter diagram
- Control charts

09/11/2014

Vinay Kalakbandi

5

SPC in services

- Natural measurement systems non-existent
- Observability is low
- Process mapping
- Value stream mapping

09/11/2014

Vinay Kalakbandi

6

Rational subgrouping

- Subgroups or samples should be selected such that
 - Chance of differences between subgroups should be maximized
 - Chance of differences due to assignable causes within a subgroup should be minimized
- Time order is the logical basis
- Snapshot approach v/s random sample approach
- Subgroup based on shifts, machines, operators etc

09/11/2014

Vinay Kalakbandi

7

Phases of Implementation

- Phase 1
 - When SPC is introduced
 - Bringing the process in control
 - Detect high levels of variation
- Phase 2
 - When major assignable causes have been detected and corrected
 - Sustaining the process in control
 - Detect low levels of variation as well
 - Before it is too late!!

09/11/2014

Vinay Kalakbandi

8

Shewart control charts

- Variable control charts
 - X-bar and R charts/s-charts
- Attribute control charts
 - p-charts and c-charts
- Iterative corrective procedure
- Impact of non-normality
- Control chart performance

09/11/2014

Vinay Kalakbandi

9

Control Chart Performance

Average Run Length

- The **average run length** (ARL) is a very important way of determining the appropriate sample size and sampling frequency.
- Let p = probability that any point exceeds the control limits. Then,

$$ARL = \frac{1}{p} \quad (15-28)$$

09/11/2014

Vinay Kalakbandi

10

Control Chart Performance

Table 15-6 Average Run Length (ARL) for an \bar{X} Chart with 3-Sigma Control Limits

Magnitude of Process Shift	ARL $n = 1$	ARL $n = 4$
0	370.4	370.4
0.5σ	155.2	43.9
1.0σ	43.9	6.3
1.5σ	15.0	2.0
2.0σ	6.3	1.2
3.0σ	2.0	1.0

Individual measurements

- When there is no basis for rational subgrouping
- Data is available relatively slowly
- Multiple measurements taken on the same unit of the product
- Continuous flow process
- Use moving range MR with the assumption that the same size is 2
- Pros and cons
 - High ARL
 - Normality assumption

The Cumulative-Sum Control Chart

- The **cusum chart** incorporates all information in the sequence of sample values by plotting the *cumulative sums* of the deviations of the sample values from a target value.
- If μ_0 is the target for the process mean, \bar{X}_j is the average of the j th sample, then the cumulative sum control chart is formed by plotting the quantity

$$C_i = \sum_{j=1}^i (\bar{X}_j - \mu_0)$$

09/11/2014

Vinay Kalakbandi

13

The Tabular or Algorithmic Cusum for monitoring the Process Mean

- Let x_i be the i th observation on the process
- If the process is in control then $x_i \sim N(\mu_0, \sigma)$
- Assume σ is known or can be estimated.
- Accumulate derivations from the target μ_0 above the target with one statistic, C^+
- Accumulate derivations from the target μ_0 below the target with another statistic, C^-
- C^+ and C^- are one-sided upper and lower cusums, respectively.

09/11/2014

Vinay Kalakbandi

14

The Tabular or Algorithmic Cusum for Monitoring the Process Mean

- The statistics are computed as follows:

The Tabular Cusum

$$C_i^+ = \max\left[0, x_i - (\mu_0 + k) + C_{i-1}^+\right]$$

$$C_i^- = \max\left[0, (\mu_0 - k) - x_i + C_{i-1}^-\right]$$

starting values are $C_0^+ = C_0^- = 0$

K is the **reference value** (or **allowance** or **slack value**)

If either statistic exceed a decision interval H , the process is considered to be out of control. Often taken as a $H = 5\sigma$

The Tabular or Algorithmic Cusum for Monitoring the Process Mean

Selecting the reference value, K

- K is often chosen halfway between the target μ_0 and the out-of-control value of the mean μ_1 that we are interested in detecting quickly.
- Shift is expressed in standard deviation units as $\mu_1 = \mu_0 + \delta\sigma$, then K is

$$K = \frac{\delta}{2} \sigma = \frac{|\mu_1 - \mu_0|}{2}$$

The Tabular or Algorithmic Cusum for Monitoring the Process Mean

Example 8-1

- $\mu_0 = 10, n = 1, \sigma = 1$
- Interested in detecting a shift of $1.0\sigma = 1.0(1.0) = 1.0$
- Out-of-control value of the process mean: $\mu_1 = 10 + 1 = 11$
- $K = \frac{1}{2}$ and $H = 5\sigma = 5$ (recommended, discussed in the next section)
- The equations for the statistics are then:

$$C_i^+ = \max\left[0, x_i - 10.5 + C_{i-1}^+\right]$$

$$C_i^- = \max\left[0, 10.5 - x_i + C_{i-1}^-\right]$$

09/11/2014


Vinay Kalakbandi

17

The Tabular or Algorithmic Cusum for Monitoring the Process Mean

Example 8-1

CUSUM Chart for x



09/11/2014

Vinay Kalakbandi

18

The Tabular or Algorithmic Cusum for Monitoring the Process Mean

Example 8-1

- The cusum control chart indicates the process is out of control.
- The next step is to search for an assignable cause, take corrective action required, and reinitialize the cusum at zero.
- If an adjustment has to be made to the process, may be helpful to estimate the process mean following the shift.

The Standardized Cusums

- It may be of interest to standardize the variable x_i .

$$y_i = \frac{x_i - \mu_0}{\sigma}$$

- The standardized cusums are then

$$C_i^+ = \max[0, y_i - k + C_{i-1}^+]$$

$$C_i^- = \max[0, k - y_i + C_{i-1}^-]$$

Improving Cusum Responsiveness for Large Shifts

- Cusum control chart is *not* as effective in detecting large shifts in the process mean as the Shewhart chart.
- An alternative is to use a **combined cusum-Shewhart procedure** for on-line control.
- The combined cusum-Shewhart procedure can improve cusum responsiveness to large shifts.

09/11/2014

Vinay Kalakbandi

21

The Fast Initial Response or Headstart Feature

- These procedures were introduced to increase sensitivity of the cusum control chart upon start-up.
- The **fast initial response (FIR)** or **headstart** sets the starting values C_0^+, C_0^- equal to some nonzero value, typically $H/2$.
- Setting the starting values to $H/2$ is called a **50 percent headstart**.

09/11/2014

Vinay Kalakbandi

22

One-Sided Cusums

- There are practical situations where a single one-sided cusum is useful.
- If a shift in only one direction is of interest then a one-sided cusum would be applicable.

The Exponentially Weighted Moving Average Control Chart

The Exponentially Weighted Moving Average Control Chart Monitoring the Process Mean

- The exponentially weighted moving average (EWMA) is defined as

$$z_i = \lambda x_i + (1 - \lambda)z_{i-1}$$

where $0 < \lambda \leq 1$ is a constant.

$z_0 = \mu_0$ (sometimes $z_0 = \bar{x}$)

8-2.1 The Exponentially Weighted Moving Average Control Chart Monitoring the Process Mean

- The control limits for the EWMA control chart are

$$UCL = \mu_0 + L\sigma \sqrt{\frac{\lambda}{(2-\lambda)} [1 - (1-\lambda)^{2i}]}$$

$$CL = \mu_0$$

$$LCL = \mu_0 - L\sigma \sqrt{\frac{\lambda}{(2-\lambda)} [1 - (1-\lambda)^{2i}]}$$

where L is the width of the control limits.

The Exponentially Weighted Moving Average Control Chart Monitoring the Process Mean

- As i gets larger, the term $[1 - (1 - \lambda)^{2i}]$ approaches infinity.
- This indicates that after the EWMA control chart has been running for several time periods, the control limits will approach **steady-state** values given by

$$UCL = \mu_0 + L\sigma \sqrt{\frac{\lambda}{(2-\lambda)}}$$

$$CL = \mu_0$$

$$LCL = \mu_0 - L\sigma \sqrt{\frac{\lambda}{(2-\lambda)}}$$

Design of an EWMA Control Chart

- The design parameters of the chart are L and λ .
- The parameters can be chosen to give desired ARL performance.
- In general, $0.05 \leq \lambda \leq 0.25$ works well in practice.
- $L = 3$ works reasonably well (especially with the larger value of λ).
- L between 2.6 and 2.8 is useful when $\lambda \leq 0.1$
- Similar to the cusum, the EWMA performs well against *small shifts* but does not react to large shifts as quickly as the Shewhart chart.
- EWMA is often *superior* to the cusum for larger shifts particularly if $\lambda > 0.1$

09/11/2014

Vinay Kalakbandi

27

Robustness of the EWMA to Non-normality

- As discussed in previously, the **individuals** control chart is **sensitive** to non-normality.
- A properly designed **EWMA** is **less sensitive** to the normality assumption.

09/11/2014

Vinay Kalakbandi

28

DNOM Charts: Deviation from Nominal

Principles

- Different parts will have different target values
- Calculate the deviation from nominal value
- Plot deviation as the quality characteristic

09/11/2014

Vinay Kalakbandi

29

Infinity Windows Sample Data

❖ Three part types:

- Header
- Right jamb
- Left jamb

❖ Nominal length varies from part to part

❖ Continuous runs; no batches


Part	Date	Time	Nominal Length	Actual Length
Right Jamb	14-Feb	6:51 AM	59.268	59.258
Header	14-Feb	6:54 AM	23	22.993
Header	14-Feb	6:56 AM	35.875	35.86
Right Jamb	14-Feb	7:00 AM	37.518	37.511
Left Jamb	14-Feb	7:08 AM	37.518	37.507
Header	14-Feb	7:12 AM	43.875	43.869
Header	14-Feb	7:14 AM	27.75	27.75
Right Jamb	14-Feb	7:15 AM	37.518	37.5169
Left Jamb	14-Feb	7:18 AM	37.518	37.5071
Header	14-Feb	10:06 AM	39.875	39.8617

09/11/2014

Vinay Kalakbandi

30

DNOM Chart



09/11/2014

Vinay Kalakbandi

31

DNOM Charts

Strengths

- Groups multiple parts and their data sets on a single chart
- Provides a continuous view of the process
- Fairly simple to construct and understand

Shortcomings

- Assumes variation is equal for all parts
- Requires some historical data to calculate control limits
- Does not address quality costs
- Only tracks within-run variation

09/11/2014

Vinay Kalakbandi

32

Standardized Control Charts

Principles

- Multiple part-types flow through a single machine
- Different parts may have different target values
- Control limits and plot points are standardized to allow charting of multiple part-types

09/11/2014

Vinay Kalakbandi

33

Standardized Control Charts

Strengths

- Groups multiple parts and their data sets on a single chart
- Provides a continuous view of the process
- Fairly simple to construct and understand
- Does not assume all parts have equal variation

Shortcomings


- Requires some historical data to calculate control limits
- Does not address quality costs
- Only tracks within-run variation

09/11/2014

Vinay Kalakbandi

34

Sample Standardized Chart



09/11/2014

Vinay Kalakbandi

35

Modified and Acceptance control charts

- When the process is highly capable
 - It might be a good idea to relax the control limits a bit
 - The relaxed control limits could be based on the specification limits.

$$\begin{aligned} \mu_L = LSL + Z_\delta \sigma & \quad UCL = USL - \left(Z_\delta - \frac{3}{\sqrt{n}} \right) \sigma & \quad = USL - \left(Z_\gamma + \frac{Z_\beta}{\sqrt{n}} \right) \sigma \\ & \quad \text{OR} \\ \mu_U = USL - Z_\delta \sigma & \quad LCL = LSL + \left(Z_\delta - \frac{3}{\sqrt{n}} \right) \sigma & \quad = LSL + \left(Z_\gamma + \frac{Z_\beta}{\sqrt{n}} \right) \sigma \end{aligned}$$

09/11/2014

Vinay Kalakbandi

36

Multiple stream processes


- Parallel and identical processes
 - Prohibitively large number of control charts
- Assignable causes might impact one or few streams at a time or all streams put together
- Use samples from the processes to formulate the control limits
- Plot max and min values across all the streams
- If the same stream is showing up as max or min value consecutively, then process out of control

09/11/2014

Vinay Kalakbandi

37

Adaptive sampling procedures



09/11/2014

Vinay Kalakbandi

38

Economic design of control charts

- Control chart design has statistical considerations only
- Cost categories to consider
 - Costs of sampling and testing
 - Costs associated with investigating an out of control signal and repair of the assignable cause
 - Costs associated with the production of non-confirming items

THANK YOU